



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Bladen PERMIT NO.: SLAS-09-07 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 5-16-12

FACILITY NAME AND ADDRESS:

Singletary Septic Tank Service
 PO Box 782
 Bladenboro, NC 28320

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Furnie Singletary Jr.
 Telephone: 910-648-2228
 Email address: N/A
 Fax: N/A

FACILITY CONTACT ADDRESS:

Same

PARTICIPANTS:

Will Burke, Environmental Senior Specialist
 Chester Cobb, Soil Scientist
 Tony Gallagher, Composting and Land Applications Branch Supervisor

STATUS OF PERMIT:

Inactive

PURPOSE OF SITE VISIT:

Routine, Audit

STATUS OF PAST NOTED VIOLATIONS:

Soil Test Follow Up

OBSERVED VIOLATIONS

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

Onsite to collect soil samples on site. Site is now inactive.

During inspection an area of "tank cleanout" was found. DWM representatives informed Singletary Septic to remove this debris from the site.

On 7-11-12 Will Burke of DWM followed up on the area mentioned above. The debris had been removed, including a depth of approximately 3 inches of soil was also removed.

Please contact me if you have any questions or concerns regarding this inspection report.



Will Burke
Regional Representative

Phone: (910) 796-7397

Sent on: 7-19-12		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
------------------	--	-------	--	---------------	---	---------	--	-------------------------